

**Leka, Kathy**

---

**From:** Humphries, Henry  
**Sent:** Monday, March 01, 2004 10:27 AM  
**To:** Leka, Kathy; Crask, Rebecca  
**Subject:** FW: Project In-service Notification

fyi

-----Original Message-----

**From:** Townlian, Cheryl L [mailto:Cheryl.Townlian@bnsf.com]  
**Sent:** Monday, March 01, 2004 10:23 AM  
**To:** 'hhumphri@icc.state.il.us'  
**Subject:** FW: Project In-service Notification

703-0018

X-12076

FYI

-----Original Message-----

**From:** enme1806@topudspd1001.iss.bnr.com  
[mailto:enme1806@topudspd1001.iss.bnr.com]  
**Sent:** Sunday, February 29, 2004 7:42 PM  
**To:** cheryl.townlian@bnsf.com  
**Subject:** Project In-service Notification

The following Warning Device project has been reported as in service.

Line segment 108, milepost -0.250, DOT # 062987E, Road Name N SEMINARY, Near GALESBURG, IL. This project was approved under Project Number T03-0018 and was placed in service on 02/26/2004.

This message is being furnished so the proper agency can be notified as necessary.

Need  
DOT

3/1/2004

W

**Leka, Kathy**

---

**From:** Humphries, Henry  
**Sent:** Monday, March 01, 2004 10:27 AM  
**To:** Leka, Kathy; Crask, Rebecca  
**Subject:** FW: Project In-service Notification

fyi

-----Original Message-----

**From:** Townlian, Cheryl L [mailto:Cheryl.Townlian@bnsf.com]  
**Sent:** Monday, March 01, 2004 10:23 AM  
**To:** 'hhumphri@icc.state.il.us'  
**Subject:** FW: Project In-service Notification

FYI

-----Original Message-----

**From:** enme1806@topudspd1001.iss.bnr.com  
[mailto:enme1806@topudspd1001.iss.bnr.com]  
**Sent:** Sunday, February 29, 2004 7:42 PM  
**To:** cheryl.townlian@bnsf.com  
**Subject:** Project In-service Notification

The following Warning Device project has been reported as in service.

Line segment 108, milepost 0.080, DOT # 062988L, Road Name S SEMINARY, Near GALESBURG,IL. This project was approved under Project Number T03-0018 and was placed in service on 02/26/2004.

This message is being furnished so the proper agency can be notified as necessary.

T03-0018  
X-12077

Rec'd  
DOT

3/1/2004

W